


# BG Quality Products

## Long Lasting Detonation Sensor Harness for Caterpillar G3520C Engine

This new detonation harness is a vast improvement over the OEM design. The OEM harness is located behind the exhaust manifold where it is exposed to heat and damage from exhaust leaks. This aftermarket harness is routed along the main engine rail and incorporates replaceable jumpers up to the sensors. If there is a leak that damages the harness jumper, simply remove the jumper by hand and install a new one. Within minutes, you are back online with little downtime or expense.



Harness shown with one jumper – see arrows  
The harness is shipped with ten jumpers (one jumper serves two cylinders)

Detonation Sensor Harness with ten jumpers: BG P/N **26425**  
Spare jumper: BG P/N **26455**

**BG**<sup>™</sup>  
The BG Service Co., Inc.  
1400 Alabama Avenue  
P.O. Box 2259  
West Palm Beach, Florida 33402-2259  
Phone (561) 659-1471  
Fax (561) 659-1728  
[SALES@BGSERVICE.COM](mailto:SALES@BGSERVICE.COM)



Please visit our website at:  
[www.bgservice.com](http://www.bgservice.com)

**Quality Products for  
Longer and Better  
Service**