

# BG Quality Products

## **SECONDARY LEADS FOR CUMMINS 8.3 L ENGINES**



### 3 Models Available:

P/N 26511-01 replaces Cummins P/N 498 9132  
and P/N 496 6863

P/N 26511-02 replaces Cummins P/N 499 4946

P/N 26511-03 replaces Cummins P/N 499 4947

Note: model shown above does not depict the OEM style coil connection of P/Ns 26511-XX (OEM style has a 90 degree connector and boot). Model above depicts the Omni and Beru coil set-up. Please call if you have any questions.



The BG Service Co., Inc.  
1400 Alabama Avenue  
P.O. Box 2259  
West Palm Beach, Florida 33402-2259  
Phone (561) 659-1471  
Fax (561) 659-1728  
[SALES@BGSERVICE.COM](mailto:SALES@BGSERVICE.COM)



CERTIFICATE NO: 131506

*Please visit our website at:*  
[www.bgservice.com](http://www.bgservice.com)

**Quality Products for  
Longer and Better  
Service**