


# BG Quality Products

## SECONDARY LEAD FOR CUMMINS 5.9 L ENGINES

P/N 26354



DS™ Connector  
Shown

**Replaces Cummins P/N 409 0567**

**Compare the supplied molded rubber boot (below left) with the industrial grade machined components included in the lead (below right).**

**The spark plug boot is fitted with a plated machined connector with a double spring (DS™) retention system.**



The BG Service Co., Inc.  
1400 Alabama Avenue  
P.O. Box 2259  
West Palm Beach, Florida 33402-2259  
Phone (561) 659-1471  
Fax (561) 659-1728  
[SALES@BGSERVICE.COM](mailto:SALES@BGSERVICE.COM)



Please visit our website at:  
[www.bgservice.com](http://www.bgservice.com)

**Quality Products for  
Longer and Better  
Service**